

# Chabad Aleph Bet Preschool

2110 East Lincoln Drive  
Phoenix, AZ

## 5 Inspection Visits Since 2023 - 5 Findings

Most recent inspection: Sep 16, 2025

● 5 Important

Across 5 inspections since 2023, the issues cited most often were The Following Deficiencies Were Observed at the Time of the Compliance Inspection Conducted on 9/16/2025 and Are Subject to Changes Pending Programmatic review.

The Compliance Officer Provided a Paper Copy of the Notice of Inspection Rights and the Small Business Bill of Rights to the Facility Staff at the Time of the Inspection.

Please Submit the Plan of Corrections via the LMS Portal Within 10 days.

\*\*\*The Director Was Reminded of the License Expiration Date and to Log on to the Port (3), The Following Deficiencies Were Observed at the Time of the Monitoring Inspection Conducted on 3/17/2025 and Are Subject to Changes Pending Programmatic Review. A Full Inspection Was Not conducted.

The Compliance Officer Provided a Paper Copy of the Notice of Inspection Rights and the Small Business Bill of Rights to the Facility Director at the Time of the Inspection.

Please Submit the Plan of Corrections via the LMS Portal Within 10 days.

3 of 3 Fingerprint Clearance Cards Reviewed (1), and There Were No Deficiencies at the Time of the Modification Inspection Conducted on 8.20.2024.

The Modification was:

1. Adding a Wall Mounted Diaper Unit to the 1's Room Located in the Portable building,
2. The Facility Enlarged a Room by Taking Down Walls in the Portable building.

The Following Was Discussed and Not Limited to:

1. The Length of the Wall Mounted Diaper Unit Does Not Accommodate the Length of the Enrolled children.
2. The Bottom of the Wall Mounted Diaper Unit Was N (1). None of the 5 findings were critical.

## Inspection Visits

**Sep 16, 2025** 1 Finding ● 1 Important

### About this report

Childery generates this report from public inspection records published by the Arizona Department of Health Services, Bureau of Child Care Licensing. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Arizona Department of Health Services, Bureau of Child Care Licensing.

- **The Following Deficiencies Were Observed at the Time of the Compliance Inspection Conducted on 9/16/2025 and Are Subject to Changes Pending Programmatic review.**

**The Compliance Officer Provided a Paper Copy of the Notice of Inspection Rights and the Small Business Bill of Rights to the Facility Staff at the Time of the Inspection.**

**Please Submit the Plan of Corrections via the LMS Portal Within 10 days.**

**\*\*\*The Director Was Reminded of the License Expiration Date and to Log on to the Port**  
Compliance (Annual)

**Mar 17, 2025** 1 Finding ● 1 Important

- **The Following Deficiencies Were Observed at the Time of the Monitoring Inspection Conducted on 3/17/2025 and Are Subject to Changes Pending Programmatic Review. A Full Inspection Was Not conducted.**

**The Compliance Officer Provided a Paper Copy of the Notice of Inspection Rights and the Small Business Bill of Rights to the Facility Director at the Time of the Inspection.**

**Please Submit the Plan of Corrections via the LMS Portal Within 10 days.**

**3 of 3 Fingerprint Clearance Cards Reviewed**  
Monitoring

**Sep 24, 2024** 1 Finding ● 1 Important

- **The Following Deficiencies Were Observed at the Time of the Compliance Inspection Conducted on 9/24/2024 and Are Subject to Changes Pending Programmatic review.**  
**\*\*\*A Follow-up Inspection Will Be conducted.**

**Please Submit the Plan of Corrections via the LMS Portal Within 10 days.**

**The Empower Self-evaluation Was Emailed to the director.**  
**The Emergency Disaster Plan Update Form Was Emailed to the director.**

**The DES Group Size Requirements Were Observed to Be Compliant at the Time of the Ins**  
Compliance (Annual)

**Aug 20, 2024** 1 Finding ● 1 Important

### About this report

Childery generates this report from public inspection records published by the Arizona Department of Health Services, Bureau of Child Care Licensing. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Arizona Department of Health Services, Bureau of Child Care Licensing.

- **There Were No Deficiencies at the Time of the Modification Inspection Conducted on 8.20.2024.**

**The Modification was:**

- 1. Adding a Wall Mounted Diaper Unit to the 1's Room Located in the Portable building,**
- 2. The Facility Enlarged a Room by Taking Down Walls in the Portable building.**

**The Following Was Discussed and Not Limited to:**

- 1. The Length of the Wall Mounted Diaper Unit Does Not Accommodate the Length of the Enrolled children.**
- 2. The Bottom of the Wall Mounted Diaper Unit Was N**

Modification

**Aug 25, 2023** 1 Finding ● 1 Important

- **The Following Deficiencies Were Found at the Time of the Compliance Inspection Conducted on 8/25/2023, and Are Subject to Changes Pending Programmatic Review.**

**Name of Compliance Officer: Jennifer Flicker**

**The Written Documentation Is Required to Be Submitted Through the Licensing Portal Within 10 Days of the Receipt of the Statement of Deficiencies.**

**\*\*Please Submit the Following documents:**

- 1) Current City of Phoenix Fire Inspection, When Obtained; and**
- 2) Foreign Degree Verification F**

Compliance (Annual)

**About this report**

Childery generates this report from public inspection records published by the Arizona Department of Health Services, Bureau of Child Care Licensing. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Arizona Department of Health Services, Bureau of Child Care Licensing.