

CVUSD - VALLE DEL SOL

51-433 EDUCATION WAY
COACHELLA, CA

2 Inspection Visits Since 2021 · 3 Findings

Most recent inspection: Oct 16, 2023

● 3 Important

Across 2 inspections since 2021, the issues cited most often were Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in That the Rubber Flooring/surface in the Outdoor Area by Play Equipment Surface Is Not in Good Repair, Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/13/2023 (1), Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in That Play Structure Is Not in Good Repair in Several Areas, Metal Flooring Was Observed Plastic Coating to Be Missing, with Areas Having Raised Pointed Parts. Also at Least Two Nuts or Bolts Were Missing. In Addition a Slide Surface Is Broken, Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/13/2023 (1), and Based on Record Review, the Licensee Did Not Comply with the Section Cited Above in That C#1,C#2 and C#3 Did Not Have a Signed Consent for Medical Treatment Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 10/07/2021 (1). None of the 3 findings were critical.

Inspection Visits

Oct 16, 2023 2 Findings ● 2 Important

- **Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in That the Rubber Flooring/surface in the Outdoor Area by Play Equipment Surface Is Not in Good Repair, Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/13/2023**

CCR 101238.2(d) Outdoor Activity Space (d) The surface of the outdoor activity space shall be maintained: This requirement is not met as evidenced by:

- **Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in That Play Structure Is Not in Good Repair in Several Areas, Metal Flooring Was Observed Plastic Coating to Be Missing, with Areas Having Raised Pointed Parts. Also at Least Two Nuts or Bolts Were Missing. In Addition a Slide Surface Is Broken, Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/13/2023**

CCR 101239(o)(1) Fixtures, Furniture, Equipment and Supplies (o) Playground equipment shall be securely anchored to the ground unless it is portable by design. (1) Equipment shall...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.

Sep 29, 2021 1 Finding ● 1 Important

- **Based on Record Review, the Licensee Did Not Comply with the Section Cited Above in That C#1,C#2 and C#3 Did Not Have a Signed Consent for Medical Treatment Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 10/07/2021**

CCR 101221(b)(8)(C) Child's Records (C) A signed consent form for emergency medical treatment unless the child's authorized representative has signed the statement specified in...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.