

DARMIS ALVAREZ

72 CONCORD ST APT 1
NEW BRITAIN, CT

1 Inspection Visit Since 2024 · 2 Findings

Most recent inspection: Apr 11, 2024

● 2 Important

Across 1 inspection since 2024, the issues cited most often were 035-Carbon Monoxide Detector (2). None of the 2 findings were critical.

Inspection Visits

Apr 11, 2024 2 Findings ● 2 Important

● **035-Carbon Monoxide Detector**

[19a-87b-9(d)(7)]

● **046-Water Temperature**

[19a-87b-9(h)]

About this report

Childery generates this report from public inspection records published by the Connecticut Office of Early Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Connecticut Office of Early Childhood.