

Tonya Jones

High Timber Road
Fort Washington, MD

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: Oct 17, 2024

● 1 Important

Across 1 inspection since 2024, the issues cited most often were LS Observed the Ceiling in the Daycare Area in Dire Need of Repair. Per the Director the Ceiling Will Be Repaired Immediately and Ls Will Do a Follow Up to View the Repairs. (1). The single finding was not critical.

Inspection Visits

Oct 17, 2024 1 Finding ● 1 Important

- **LS Observed the Ceiling in the Daycare Area in Dire Need of Repair. Per the Director the Ceiling Will Be Repaired Immediately and Ls Will Do a Follow Up to View the Repairs.**

13A.15.05.01B

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.