

Little Village Learning LLC

31st Street
Mount Rainier, MD

1 Inspection Visit Since 2025 - 1 Finding

Most recent inspection: Nov 10, 2025

● 1 Important

Across 1 inspection since 2025, the issues cited most often were Specialist Observed a Hole in the Wall Near the Floor Next to the Countertop in the Basement of the Home. (1). The single finding was not critical.

Inspection Visits

Oct 23, 2025 1 Finding ● 1 Important

● **Specialist Observed a Hole in the Wall Near the Floor Next to the Countertop in the Basement of the Home.**

13A.15.05.01B

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.