

Trinity Child Care Center

Good Luck Road
Lanham, MD

1 Inspection Visit Since 2026 · 3 Findings

Most recent inspection: Mar 13, 2026

● 3 Important

Across 1 inspection since 2026, the issues cited most often were LS Observed Four Classrooms During the Change of Operation Inspection. The Director Is Requesting to Open a Schoolage Room, Infant Room, Toddler Room and a Preschool Room. Pending the Required Paperwork for the Change of Operation Inspection. During the Change of Operation the Rooms Were Not Set Up (1), LS Observed Evidence of Missing Floor Tiles and Wall Boarder Cover in Room 19. LS Observed Chipping Paint Located by the Window in Room 18. Corrected on Site. (1), and LS Observed Evidence of Electric Cords Hanging and Accessible to the Children in Room 17. Corrected on Site (1). None of the 3 findings were critical.

Inspection Visits

Mar 13, 2026 3 Findings ● 3 Important

● **LS Observed Four Classrooms During the Change of Operation Inspection. The Director Is Requesting to Open a Schoolage Room, Infant Room, Toddler Room and a Preschool Room. Pending the Required Paperwork for the Change of Operation Inspection. During the Change of Operation the Rooms Were Not Set Up**
13A.16.03.07A

● **LS Observed Evidence of Missing Floor Tiles and Wall Boarder Cover in Room 19. LS Observed Chipping Paint Located by the Window in Room 18. Corrected on Site.**
13A.16.05.01A(1)

● **LS Observed Evidence of Electric Cords Hanging and Accessible to the Children in Room 17. Corrected on Site**
13A.16.10.04A

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.