

RADIANT FAITH ACADEMY

5314 W FLORISSANT AVE
ST LOUIS, MO

1 Inspection Visit Since 2025 - 5 Findings

Most recent inspection: Dec 12, 2025

● 5 Important

Across 1 inspection since 2025, the issues cited most often were Evidence of Local Zoning Approval Was Not Received. (3) and The Ceilings Located in the Tod 2 Class Was/were Not in Good Condition as Evidenced by Water Observed Leaking From One Ceiling Tile. (2). None of the 5 findings were critical.

Inspection Visits

Dec 12, 2025 5 Findings ● 5 Important

● **Evidence of Local Zoning Approval Was Not Received.**

5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Conducted.**

5 CSR 25-500.052 Annual Requirements

● **Evidence of Local Zoning Approval Was Not Received.**

5 CSR 25-500.052 Annual Requirements

● **The Ceilings Located in the Tod 2 Class Was/were Not in Good Condition as Evidenced by Water Observed Leaking From One Ceiling Tile.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

● **The Walls Located in the Tod 1 Class Was/were Not in Good Condition as Evidenced by Mildew Stains Present One One Wall in the Tod 2 Class.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.