

WILLIAMS TOWNSHIP PRE-K

10400 JAMES B WHITE HWY SOUTH
WHITEVILLE, NC

4 Inspection Visits Since 2024 · 5 Findings · 20% Corrected at Visit

Most recent inspection: Apr 23, 2026

● 5 Important

Across 4 inspections since 2024, the issues cited most often were The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment. (1), A Safe Indoor and Outdoor Environment Was Not Provided for the Children. (1), and A Child Care Operator Did Not Notify the Division of Any New Child Care Providers, as Defined in G.S. 110-90.2(a)(2), Who Were Hired or Moved Into the Child... (1). None of the 5 findings were critical.

Inspection Visits

Apr 23, 2026 1 Finding ● 1 Important

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The mulch around the slides and the ladder of the stationary climber measured at 1-3 inches. Violation confirmed corrected by letter received from provider on 4/24/2026

Sep 8, 2025 2 Findings ● 2 Important

● **A Safe Indoor and Outdoor Environment Was Not Provided for the Children.**

The paint is chipping and peeling off the white, blue, yellow and red climber. The metal frame is rusty where the paint is missing. The chipping paint has jagged and sharp edges that are a potential hazard. Viol

● **A Child Care Operator Did Not Notify the Division of Any New Child Care Providers, as Defined in G.S. 110-90.2(a)(2), Who Were Hired or Moved Into the Child...**

care facility within five business days. The facility has not completed the ABCMS training and linked their staff to their facil

Sep 12, 2024 1 Finding ● 1 Important

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

- **Monthly Playground Inspections Were Not Completed And/or They Were Not Completed by an Individual Trained in Playground Safety Requirements.**

A monthly playground inspection has not been documented since May 2024. Violation corrected during visit

Corrected at visit

Mar 13, 2024 1 Finding ● 1 Important

- **Center Has Not Passed Required Sanitation Inspection and Received an Approved or Superior Rating.**

A sanitation inspection has not been conducted since March 1, 2023, over one year ago. Violation confirmed corrected by letter received from provider on 4/15/2024

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.