

BAMBINO'S PLAYSCHOOL

3404 DAVIS DR
CARY, NC

1 Inspection Visit Since 2023 - 3 Findings - 0% Corrected at Visit

Most recent inspection: Nov 20, 2023

● 3 Important

Across 1 inspection since 2023, the issues cited most often were A Safe Indoor and Outdoor Environment Was Not Provided for the Children. (1), Air Conditioning Units Were Accessible or Did Not Have a Guard to Keep Objects From Being Thrown Into the Unit. (1), and The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment. (1). None of the 3 findings were critical.

Inspection Visits

Nov 20, 2023 3 Findings ● 3 Important

● **A Safe Indoor and Outdoor Environment Was Not Provided for the Children.**

The protective barrier on the first step of the large play structure on the big playground has fallen off leaving a metal edge exposed. Violation confirmed corrected by letter received from provider on 12/4/2023

● **Air Conditioning Units Were Accessible or Did Not Have a Guard to Keep Objects From Being Thrown Into the Unit.**

The AC unit on the big playground does have the protective barrier but one of the slats is missing from the wooden fence around the AC unit leaving a space a child could fit

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

Mulch did not measure the required 6 inches deep under the monkey bars and play structure on the 3-5 year old playground. Violation confirmed corrected by letter received from provider on 12/4/2023

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.