

Bernier, Rocio

6711 Bayfield Ave
Far Rockaway, NY

1 Inspection Visit Since 2026 · 2 Findings · 100% Corrected at Visit

Most recent inspection: Apr 2, 2026

● 2 Important

Across 1 inspection since 2026, the issues cited most often were The Emergency Evacuation Diagram Must Be Posted in a Visible Location. (2). None of the 2 findings were critical.

Inspection Visits

Apr 2, 2026 2 Findings ● 2 Important

● **The Emergency Evacuation Diagram Must Be Posted in a Visible Location.**

417.5(b)(2)

Corrected at visit

● **Radiators and Pipes Located in Rooms Occupied by Children Must Be Covered to Protect the Children From Injury When the Heating System Is in Use.**

417.5(d)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.