

Shepherd Holdings Inc.

984 Sutter Avenue
Brooklyn, NY

2 Inspection Visits Since 2025 - 5 Findings - 80% Corrected at Visit

Most recent inspection: Jan 20, 2026

● 5 Important

Across 2 inspections since 2025, the issues cited most often were Evacuation Drills Must Be Conducted at Least Monthly During Various Hours of Operation of the School Age Child Care Program. (2), Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard. (2), and All Clearances Required Pursuant to Subdivision (A) of This Section; And (1). None of the 5 findings were critical.

Inspection Visits

Jan 20, 2026 3 Findings ● 3 Important

● **All Clearances Required Pursuant to Subdivision (A) of This Section; And**
413.4(b)(1)

Corrected at visit

● **Evacuation Drills Must Be Conducted at Least Monthly During Various Hours of Operation of the School Age Child Care Program.**
414.4(b)(1)

● **All Fire Alarm and Detection Systems Must Be Inspected, Tested and Maintained in Accordance with the Applicable Requirements of Fire Code and Building Code of N**
414.4(d)

Corrected at visit

Apr 24, 2025 2 Findings ● 2 Important

● **Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard.**
414.5(a)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.

- **Whenever the Heating System Is in Use, Pipes and Radiators Accessible to Children Must Have Barriers or Covers to Protect Children From Injury, Unless Rooms Are**

414.5(d)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.