

The Young Men's Christian Association of the Capital District

30 Pashley Road
Scotia, NY

1 Inspection Visit Since 2026 · 3 Findings · 0% Corrected at Visit

Most recent inspection: Feb 20, 2026

● 3 Important

Across 1 inspection since 2026, the issues cited most often were All Fire Alarm and Detection Systems Must Be Inspected, Tested and Maintained in Accordance with the Applicable Requirements of Fire Code and Building Code of N (2) and Buildings, Systems and Equipment Must Be Kept in Good Repair and Operate as Designed. (1). None of the 3 findings were critical.

Inspection Visits

Feb 20, 2026 3 Findings ● 3 Important

- **Buildings, Systems and Equipment Must Be Kept in Good Repair and Operate as Designed.**
414.3(l)(2)
- **All Fire Alarm and Detection Systems Must Be Inspected, Tested and Maintained in Accordance with the Applicable Requirements of Fire Code and Building Code of N**
414.4(d)
- **The Director or a Designated Qualified Staff Member Must Conduct Monthly Inspections of the Premises to Observe Possible Fire and Safety Hazards. Any Such Hazar**
414.4(h)

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.