

Santos, Francisco

1229 Clay Avenue
Bronx, NY

2 Inspection Visits Since 2026 - 4 Findings - 75% Corrected at Visit

Most recent inspection: May 13, 2026

● 4 Important

Across 2 inspections since 2026, the issues cited most often were Protective Caps, Covers or Permanently Installed Obstructive Devices Must Be Used on All Electrical Outlets That Are Accessible to Children. (2), Evacuation Drills Must Be Conducted at Least Monthly During the Hours of Operation of the Group Family Day Care Home. (1), and Peeling or Damaged Paint or Plaster Must Be Repaired. (1). None of the 4 findings were critical.

Inspection Visits

May 13, 2026 2 Findings ● 2 Important

- **Evacuation Drills Must Be Conducted at Least Monthly During the Hours of Operation of the Group Family Day Care Home.**

416.4(b)(1)

- **Protective Caps, Covers or Permanently Installed Obstructive Devices Must Be Used on All Electrical Outlets That Are Accessible to Children.**

416.5(i)

Corrected at visit

Mar 31, 2026 2 Findings ● 2 Important

- **Peeling or Damaged Paint or Plaster Must Be Repaired.**

416.3(h)

Corrected at visit

- **Windows Above the First Floor, Other Than Those Identified for Emergency Evacuation, That Are Accessible to Children and Which Present a Fall Hazard Must Be Pro**

416.5(q)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.