

The Booker T. Washington Community Center of Auburn, N.Y., Inc.

2 North Herman Ave.
Auburn, NY

1 Inspection Visit Since 2025 · 2 Findings · 100% Corrected at Visit

Most recent inspection: Dec 16, 2025

● 2 Important

Across 1 inspection since 2025, the issues cited most often were All Buildings Used for School-age Child Care Programs Must Remain in Compliance with the Applicable Provisions of the Fire Code and Building Code of New York St (1) and The Emergency Evacuation Diagram, as Approved by the Office, Must Be Posted in a Conspicuous Place in Every Room Used by the School Age Child Care Program. (1). None of the 2 findings were critical.

Inspection Visits

Dec 16, 2025 2 Findings ● 2 Important

- **All Buildings Used for School-age Child Care Programs Must Remain in Compliance with the Applicable Provisions of the Fire Code and Building Code of New York St**

414.3(l)

Corrected at visit

- **The Emergency Evacuation Diagram, as Approved by the Office, Must Be Posted in a Conspicuous Place in Every Room Used by the School Age Child Care Program.**

414.5(b)(2)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.