

SOFIS LITTLE CASTLE LLC

8915 104 st
Richmond hill, NY

1 Inspection Visit Since 2025 - 1 Finding - 100% Corrected at Visit

Most recent inspection: Jun 11, 2025

● 1 Important

Across 1 inspection since 2025, the issues cited most often were Porches, Decks or Stairs with More Than Two Steps Must Have Railings with a Barrier Extending to the Floor or Ground to Prevent Children From Falling. Acceptabl (1). The single finding was not critical.

Inspection Visits

Jun 11, 2025 1 Finding ● 1 Important

- **Porches, Decks or Stairs with More Than Two Steps Must Have Railings with a Barrier Extending to the Floor or Ground to Prevent Children From Falling. Acceptabl**

416.5(e)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.