

Graham Windham Inc. `

530 West 133rd Street

New York, NY

3 Inspection Visits Since 2024 · 5 Findings · 100% Corrected at Visit

Most recent inspection: Nov 19, 2025



Across 3 inspections since 2024, the issues cited most often were Peeling or Damaged Paint or Plaster Must Be Repaired. (4) and The Program Must Maintain on File at the Program, Available for Inspection by the Office or Its Designees at Any Time, the Following Records in a Current and Ac (1). None of the 5 findings were critical.

Inspection Visits

Nov 19, 2025

1 Finding

● 1 Important

- **Peeling or Damaged Paint or Plaster Must Be Repaired.**
414.3(g)

Corrected at visit

Oct 15, 2025

3 Findings

● 3 Important

- **The Program Must Maintain on File at the Program, Available for Inspection by the Office or Its Designees at Any Time, the Following Records in a Current and Ac**
414.15(c)(11)

Corrected at visit

- **Peeling or Damaged Paint or Plaster Must Be Repaired.**
414.3(g)

Corrected at visit

- **Buildings, Systems and Equipment Must Be Kept in Good Repair and Operate as Designed.**
414.3(l)(2)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.

Jun 24, 2024 1 Finding — 1 Important

● **Peeling or Damaged Paint or Plaster Must Be Repaired.**

414.3(g)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.