

# LCSI - QUAIL CREEK

11700 THORN RIDGE RD  
OKLAHOMA CITY, OK

## 5 Inspection Visits Since 2025 - 2 Findings

Most recent inspection: May 13, 2026



● 2 Important

Across 5 inspections since 2025, the issues cited most often were Program Was Unable to Provide a Contract with the Company Used That Continuously Monitors the Central Detection and Alarm System for Smoke and Carbon Monoxide System for Full-function. (2). None of the 2 findings were critical.

## Inspection Visits

**May 13, 2026** 1 Finding ● 1 Important

- **Program Was Unable to Provide a Contract with the Company Used That Continuously Monitors the Central Detection and Alarm System for Smoke and Carbon Monoxide System for Full-function.**

Periodic - Full

**Nov 18, 2025** 1 Finding ● 1 Important

- **Program Was Unable to Provide Documentation of the Company the School Uses to Monitoring the Central Detection and Alarm System for Smoke and Carbon Monoxide.**

Periodic - Full

### About this report

Childery generates this report from public inspection records published by the Oklahoma Department of Human Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Oklahoma Department of Human Services, Child Care Services.