

KENWOOD HEAD START

1210 CR 487 RD
KENWOOD, OK

5 Inspection Visits Since 2025 · 1 Finding

Most recent inspection: Apr 13, 2026



● 1 Important

Across 5 inspections since 2025, the issues cited most often were Fire Extinguishers Are Tagged as Last Serviced May 24 (1). The single finding was not critical.

Inspection Visits

Aug 18, 2025 1 Finding ● 1 Important

● **Fire Extinguishers Are Tagged as Last Serviced May 24**

Periodic - Full

the last checklist was completed in June of 24 and is out of date | Equipment Inventory was last completed in June of 24 and is out of date

About this report

Childery generates this report from public inspection records published by the Oklahoma Department of Human Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Oklahoma Department of Human Services, Child Care Services.