

GymKix

1352 MATTHEW SPICER RD

COPPERAS COVE, TX

1 Inspection Visit Since 2026 · 1 Finding

Most recent inspection: Jan 16, 2026



1 Critical

Across 1 inspection since 2026, the issues cited most often were Electric or Battery-Operated Carbon Monoxide Detector-Install New Battery in Each CO Detector Annually (1). The single finding was critical.

Inspection Visits

Jan 16, 2026 1 Finding 1 Critical

- Electric or Battery-Operated Carbon Monoxide Detector-Install New Battery in Each CO Detector Annually
746.5537(a)(1)

About this report

Childery generates this report from public inspection records published by the Texas Health and Human Services Commission. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Texas Health and Human Services Commission.