

Children's Social Expo

2021 ACKLEN RUN DR
ROSHARON, TX

3 Inspection Visits Since 2025 · 3 Findings

Most recent inspection: Sep 26, 2025

● 3 Critical

Across 3 inspections since 2025, the issues cited most often were Measurement of Use Zone for Swings - in Front and Rear (1), Prohibited Equipment - Rings,Trapeze Bars, Free-Swinging Ropes (1), and Installation of Smoke Detectors (1). Of 3 total findings, 3 were critical.

Inspection Visits

Sep 26, 2025 1 Finding ● 1 Critical

● Measurement of Use Zone for Swings - in Front and Rear
747.4607(a)

Sep 15, 2025 1 Finding ● 1 Critical

● Prohibited Equipment - Rings,Trapeze Bars, Free-Swinging Ropes
747.4403(4)

Sep 12, 2025 1 Finding ● 1 Critical

● Installation of Smoke Detectors
747.5113

About this report

Childery generates this report from public inspection records published by the Texas Health and Human Services Commission. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Texas Health and Human Services Commission.