

DIVINE NEW BEGINNINGS

4300 MYRTLE CT B
RACINE, WI

3 Inspection Visits Since 2025 - 18 Findings

Most recent inspection: Feb 17, 2026

● 18 Important

Across 3 inspections since 2025, the issues cited most often were Prior To A Child's First Day Of Attendance For Any Child In (9) and 202.08(12)(f)1-4 (9). None of the 18 findings were critical.

Inspection Visits

Feb 17, 2026 4 Findings ● 4 Important

● **Prior To A Child's First Day Of Attendance For Any Child In**

202.08(12)(f)1-4

1. The Parents' Home And Work Phone Numbers.

● **Before Transporting A Child, An Operator Shall Obtain Signed**

202.08(9)(b)

Children 4-9 missing signed transportation permission forms.

● **202.08(12)(f)1-4**

Rule Number

Rule Summary

● **202.08(9)(b)**

Rule Number

Rule Summary

Sep 18, 2025 8 Findings ● 8 Important

● **A Safe Crib Or Playpen With A Tight-Fitting Mattress With A**

202.08(11)(d)

Provider's playpen had stuffed animals in it.

About this report

Childery generates this report from public inspection records published by the Wisconsin Department of Children and Families, Bureau of Early Care Regulation. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Wisconsin Department of Children and Families, Bureau of Early Care Regulation.

● **All Exits Shall Be Clear Of Obstruction.**

202.08(2)(a)1.

2nd exit is a window, however, the escape ladder was not assembled nor was there a stool or step for children to reach t

● **The Home Shall Have A Functional Smoke Detector On Each Floor**

202.08(2)(ar)

Smoke detector on the 2nd floor not in working order.

● **An Operator Shall Ensure That A Written List Of Children Bei**

202.08(9)(c)

Provider did not have copies of completed permissions and emergency information for each child in the vehicle.

● **202.08(2)(a)1.**

Rule Number

Rule Summary

● **202.08(2)(ar)**

Rule Number

Rule Summary

● **202.08(11)(d)**

Rule Number

Rule Summary

● **202.08(9)(c)**

Rule Number

Rule Summary

Jan 14, 2025 6 Findings ● 6 Important

● **A One-Unit Or Two-Unit Residential Building Shall Have A Fun**

202.08(2)(am)1.

The 2nd floor needs a carbon monoxide detector installed.

● **The Home Shall Have A Functional Smoke Detector On Each Floor**

202.08(2)(ar)

The 2nd floor needs a smoke detector installed.

About this report

Childery generates this report from public inspection records published by the Wisconsin Department of Children and Families, Bureau of Early Care Regulation. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Wisconsin Department of Children and Families, Bureau of Early Care Regulation.

● **The Indoor And Outdoor Areas Of The Home Shall Be Free Of Ha**

202.08(2)(c)

Cords accessible to children next to the TV as well as a Christmas tree with cords and potentially dangerous ornaments.

● **202.08(2)(am)1.**

Rule Number

Rule Summary

● **202.08(2)(ar)**

Rule Number

Rule Summary

● **202.08(2)(c)**

Rule Number

Rule Summary

About this report

Childery generates this report from public inspection records published by the Wisconsin Department of Children and Families, Bureau of Early Care Regulation. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Wisconsin Department of Children and Families, Bureau of Early Care Regulation.