

NISHIMOTO STATE PRESCHOOL

26460 MARTIN ST
MADERA, CA

2 Inspection Visits Since 2024 · 2 Findings

Most recent inspection: Aug 19, 2025

● 2 Important

Across 2 inspections since 2024, the issues cited most often were Based on Observation, the Licensee Did Not Comply with the Section Cited Above in That LPA Observed, Fading Paint on the Hanging Bar, a Blocked-off Area (By a Wood Panel) on the Play Equipment That Is in Disrepair, Missing Hand and Foot Holds From the Climbing Equipment. LPA Observed a Large Gap on the Ground Near a Building Adjacent to the Playground, Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 09/05/2025 (2). None of the 2 findings were critical.

Inspection Visits

Aug 19, 2025 1 Finding ● 1 Important

- **Based on Observation, the Licensee Did Not Comply with the Section Cited Above in That LPA Observed, Fading Paint on the Hanging Bar, a Blocked-off Area (By a Wood Panel) on the Play Equipment That Is in Disrepair, Missing Hand and Foot Holds From the Climbing Equipment. LPA Observed a Large Gap on the Ground Near a Building Adjacent to the Playground, Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 09/05/2025**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

Nov 15, 2024 1 Finding ● 1 Important

- **Based on Observation, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA and LPM Observed Multiple Holes on the Cushioning Pad at the Play Structure Area. LPA and LPM Observed Chipped Paint on the Stair Area on the Play Structure and Fading Paint on the Hanging Bar. LPA and LPM Observed Cracked Covering on the Climbing Chain. Head Custodian Stated a Work Order Has Been Made for a Replacement of the Cushioning Pad but Facility Is Still in the Process of Approving a Bid by a Contractor. POC Due Date: 12/16/2024**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.