

KINDERCARE LEARNING CENTER - BRUCEVILLE

9394 BRUCEVILLE ROAD
ELK GROVE, CA

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: Feb 5, 2024

● 1 Important

Across 1 inspection since 2024, the issues cited most often were Based on LPA Observation, the Licensee Did Not Comply with the Section Cited Above When the Preschool Playground Has an Uneven Surface with Cracks and a Hard Surface Under the Play Structures Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 05/06/2024 (1). The single finding was not critical.

Inspection Visits

Feb 5, 2024 1 Finding ● 1 Important

- **Based on LPA Observation, the Licensee Did Not Comply with the Section Cited Above When the Preschool Playground Has an Uneven Surface with Cracks and a Hard Surface Under the Play Structures Which Poses/posed a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 05/06/2024**

CCR 101238.2(e) Outdoor Activity Space (e) As a condition of licensure, the areas around and under high climbing equipment, swings, slides and other similar equipment shall be...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.