

KENTER STAR

645 N. KENTER AVE
LOS ANGELES, CA

1 Inspection Visit Since 2022 · 1 Finding

Most recent inspection: Oct 31, 2022

● 1 Important

Across 1 inspection since 2022, the issues cited most often were Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in a Wooden Panel Fence Gate Located Along the Side of the Yard That Keeps Children Away From the Dumpster Area Is in Need of Repair Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/21/2022 (1). The single finding was not critical.

Inspection Visits

Oct 31, 2022 1 Finding ● 1 Important

- **Based on Observation and Interview, the Licensee Did Not Comply with the Section Cited Above in a Wooden Panel Fence Gate Located Along the Side of the Yard That Keeps Children Away From the Dumpster Area Is in Need of Repair Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 11/21/2022**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.