

ALISO PICO PRESCHOOL

1505 E. 1ST STREET
LOS ANGELES, CA

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: Jun 21, 2024

● 1 Important

Across 1 inspection since 2024, the issues cited most often were Based on Observation and Interview, the Facility Did Not Comply with the Section Cited Above In, LPA Observed an 8in Blue Bucket of Water Filled to the Top. Per Teacher Pricilla That Has Always Been There Because the Teachers Use That Water Outlet to Get Water but Is Aware That Water Outlet Is Leaking Which Poses an Immediate Danger to the Health and Safety of the Children. LPA Obtained Video and Photos. LPA Also Observed Classroom Doors That Lead to Public Area to Be Accessiable to Children and the Push Latch to Be at Childs Level Which Gives Children Easy Access to Public. Main Entrance and Exit Door Does Not Conatain an Alram and the Push Handle Is Placed at Childs Level. Exit Door That Leads to Public Access Is Easliy Accessiable to Children with the Turn of the Knob, Which Poses an Immediate Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 06/26/2024 (1). The single finding was not critical.

Inspection Visits

Jun 21, 2024 1 Finding ● 1 Important

- **Based on Observation and Interview, the Facility Did Not Comply with the Section Cited Above In, LPA Observed an 8in Blue Bucket of Water Filled to the Top. Per Teacher Pricilla That Has Always Been There Because the Teachers Use That Water Outlet to Get Water but Is Aware That Water Outlet Is Leaking Which Poses an Immediate Danger to the Health and Safety of the Children. LPA Obtained Video and Photos. LPA Also Observed Classroom Doors That Lead to Public Area to Be Accessiable to Children and the Push Latch to Be at Childs Level Which Gives Children Easy Access to Public. Main Entrance and Exit Door Does Not Conatain an Alram and the Push Handle Is Placed at Childs Level. Exit Door That Leads to Public Access Is Easliy Accessiable to Children with the Turn of the Knob, Which Poses an Immediate Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 06/26/2024**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.