

JOHN C. FREMONT SCHOOL

1120 WEST 22ND ST.
MERCED, CA

2 Inspection Visits Since 2023 · 2 Findings

Most recent inspection: Feb 13, 2026

● 2 Important

Across 2 inspections since 2023, the issues cited most often were Based on LPA Observations and Site (1) and Based on Observation During Inspection of Classroom, the Licensee Did Not Comply with the Section Cited Above in That One Out of One Carbon Monoxide Detector Did Not Function During the Test, Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 08/31/2023 (1). None of the 2 findings were critical.

Inspection Visits

Feb 13, 2026 1 Finding ● 1 Important

● **Based on LPA Observations and Site**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

Aug 24, 2023 1 Finding ● 1 Important

● **Based on Observation During Inspection of Classroom, the Licensee Did Not Comply with the Section Cited Above in That One Out of One Carbon Monoxide Detector Did Not Function During the Test, Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 08/31/2023**

HSC 1596.954 Every licensed child day care center shall have one or more carbon monoxide detectors in the facility that meet the standards established in Chapter 8 (commencing...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.