

CHILDREN'S MONTESSORI SCHOOL

8736 BAKER AVENUE
RANCHO CUCAMONGA, CA

2 Inspection Visits Since 2023 · 3 Findings

Most recent inspection: Apr 24, 2025

● 3 Important

Across 2 inspections since 2023, the issues cited most often were Based on Observation, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA Observed an Air Vent with Sharp Edges Accessible to the Children and Could Be a Potential Hazard, Window Cells That Are Dirty, Blinds That Are Dirty and Stucko Coming Off and Paint Coming Off in the Area Where the Sinks Are in the Classroom. POC Due Date: 05/08/2025 (2) and Based on Observation, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA Observed All Pool Requirements Were Not Met. LPA Observed the Life Ring, the Pole with the Body Hook and the Observation Log Were Not Available or Visable During the Inspection. POC Due Date: 05/08/2025 (1). None of the 3 findings were critical.

Inspection Visits

Apr 24, 2025 2 Findings ● 2 Important

- **Based on Observation, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA Observed an Air Vent with Sharp Edges Accessible to the Children and Could Be a Potential Hazard, Window Cells That Are Dirty, Blinds That Are Dirty and Stucko Coming Off and Paint Coming Off in the Area Where the Sinks Are in the Classroom. POC Due Date: 05/08/2025**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

- **Based on Observation, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA Observed All Pool Requirements Were Not Met. LPA Observed the Life Ring, the Pole with the Body Hook and the Observation Log Were Not Available or Visable During the Inspection. POC Due Date: 05/08/2025**

HSC 1596.814(b)(3) Pool Safety (b) A licensed daycare center with an in-ground swimming pool on the premises shall comply with all of the following requirements: (3) The licensee...

Jun 22, 2023 1 Finding ● 1 Important

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.

- **Based on Observation, the Licensee Did Not Comply with the Section Cited Above in Objects Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. LPA Observed the Two Urnals in the Boy's Bathroom Are Leaking Water and Will Need to Be Repaired or Replaced. POC Due Date: 06/29/2023**

CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.