

KIDS KASTLE PRESCHOOL

2525 FAIRVIEW ROAD
COSTA MESA, CA

3 Inspection Visits Since 2021 · 6 Findings

Most recent inspection: Nov 4, 2025

● 6 Important

Across 3 inspections since 2021, the issues cited most often were Based on LPA Observation and Interview, the Licensee Did Not Comply with the Section Cited Above as LPA Observed a Broken Fence Pole, Missing Pieces of Privacy Fence, and Broken Toys/equipment Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 12/02/2025 (2), Based on LPA Observation and Interview the Licensee Did Not Comply with the Section Cited Above as LPA Observed a Torn Carpet (Approximately 1 Inch X 10 Inches), Dirt on the Diaper Changing Table, Power Outlet Without Covers, and Scraped Wall with Plaster Exposed Approximately 2 Inches in Diameter Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 12/02/2025 (1), and Based on Interview, the Facility Did Not Comply with the Section Cited Above. The Director Stated the Facility Has Not Conducted the Water Lead Testing. This Poses a Potential Health, Safety Risk to Children in Care. POC Due Date: 12/08/2023 (1). None of the 6 findings were critical.

Inspection Visits

Nov 4, 2025 2 Findings ● 2 Important

- **Based on LPA Observation and Interview, the Licensee Did Not Comply with the Section Cited Above as LPA Observed a Broken Fence Pole, Missing Pieces of Privacy Fence, and Broken Toys/equipment Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 12/02/2025**
CCR 101238.2(d)(2) Outdoor Activity Space (d) The surface of the outdoor activity space shall be maintained: (2) Free of hazards including, but not limited to, holes, broken glass...

- **Based on LPA Observation and Interview the Licensee Did Not Comply with the Section Cited Above as LPA Observed a Torn Carpet (Approximately 1 Inch X 10 Inches), Dirt on the Diaper Changing Table, Power Outlet Without Covers, and Scraped Wall with Plaster Exposed Approximately 2 Inches in Diameter Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. POC Due Date: 12/02/2025**
CCR 101238(a) Buildings and Grounds (a) The child care center shall be clean, safe, sanitary and in good repair at all times to ensure the safety and well-being of children,...

Nov 8, 2023 2 Findings ● 2 Important

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.

- **Based on Interview, the Facility Did Not Comply with the Section Cited Above. The Director Stated the Facility Has Not Conducted the Water Lead Testing. This Poses a Potential Health, Safety Risk to Children in Care. POC Due Date: 12/08/2023**

HSC 1597.16(a)(1) Lead Testing (1) A licensed child day care center, as defined in Section 1596.76, that is located in a building that was constructed before January 1, 2010,...

- **Based on Observation and Interview, the Facility Did Not Comply with the Section Cited Above. The Director Stated the Facility Has Not Conducted the Water Lead Testing and Has Not Received and Posted Results. This Poses a Potential Health, Safety Risk to Children in Care. POC Due Date: 12/08/2023**

WD 100700(c)(1) Written Directives for Lead Testing (1) For a license issued on or after July 1, 2022, initial testing results shall be received and posted within 180 days of...

Nov 18, 2021 2 Findings ● 2 Important

- **Based on Observation of the Outdoor Play Area of the Preschool, the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. It Was Observed That Some of the Plastic Play Structures Had Holes and Were in Disrepair. POC Due Date: 12/09/2021**

CCR 101238.2(d)(2) Outdoor Activity Space (d) The surface of the outdoor activity space shall be maintained: (2) Free of hazards including, but not limited to, holes, broken glass...

- **Based on Staff Record Review the Licensee Did Not Comply with the Section Cited Above Which Poses a Potential Health, Safety or Personal Rights Risk to Persons in Care. Of the 12 Staff Files Reviewed 11 Did Not Have Current Mandated Reporter Training Certificates to Review. POC Due Date: 12/09/2021**

HSC 1596.8662(b)(1) Administration of Child Day Care Licensing (1) On or before March 30, 2018, a person who, on January 1, 2018, is a licensed child day care provider,...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.