

# WALKERS DAY CARE CENTER

9909 BLUE RIDGE BLVD  
KANSAS CITY, MO

## 2 Inspection Visits Since 2025 - 5 Findings

Most recent inspection: Jan 9, 2026

● 5 Important

Across 2 inspections since 2025, the issues cited most often were The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured Approximately 5 - 6 Inches at the 2 Gates on Ea (5). None of the 5 findings were critical.

## Inspection Visits

**Jan 9, 2026** 4 Findings ● 4 Important

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured Approximately 5 - 6 Inches at the 2 Gates on Ea**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by There Was a Tree Branch Hanging Low From the Back Tree on the Playground That Was Dangling From the Tree.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured Approximately 5 - 6 Inches at the 2 Gates on Ea**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by There Was a Tree Branch Hanging Low From the Back Tree on the Playground That Was Dangling From the Tree.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

**Dec 18, 2025** 1 Finding ● 1 Important

### About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured Approximately 5 - 6 Inches at the 2 Gates on Ea**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

#### **About this report**

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.